



Specialists in 3D profiling

Gashose Replacement

Reduce the risk of hosefire



Gas hoses are vulnerable to leakage when not replaced biannually. Exposure to heat and repetitive motion in thermal cutting can cause leakage, fire or an explosion. Regular inspection of the gas installation by competent technicians is required to ensure the safe operation of the machine.

It is strongly recommended that oxygen and flammable gas hoses are replaced every two years in all CNC Machines.

- ① No leakage
- ② No fire
- ③ No explosion

Recommended HGG Service includes:

- > Replacement hose set
- > Installation on site
- > Inspection of complete gas installation including valves



Free diagnostic call?

Let us discuss your needs.
Contact us now!

HGG SERVICES WORLDWIDE

Europe & MEIA

+31 227 504188

service@hgg.nl

Americas

+1 83 34444872

service@hgg-usa.com

Asia Pacific

+65 31 636217

service@hgg-asia.com